

Release notes for 5.2.14:

Applicable Product: Nyquist E7000, and Nyquist C4000

Applicable Releases: Nyquist E7000 10.0.0:575 / 10.0.1:575 and Nyquist C4000 7.0.0:535 / 7.0.1:535

Fixed in Releases: Nyquist E7000 11.0.0, Nyquist C4000 11.0.0 and higher

Firmware File Name: NyqUpdate-5.2.14.tar.gz

How to apply updated firmware: Use "Firmware" view of the Nyquist web interface.

This new Nyquist appliance firmware version (NyqUpdate-5.2.14.tar.gz) provides the following fixes:

[NYQ-8169] [NYQ-8172] Fixed issue where some VoIP NQ-S1810WT, NQ-S1810CT, or NQ-S1810WBC appliances with attached NQ-E7020 Digital Call Switches would make phantom calls.

[NYQ-8186] Fixed issue where user is unable to make station-based page to channel C of bridged 4-channel amplifier NQ-A4XXX.

[NYQ-8244] Fixed issue where some NQ-A2XXX and NQ-A4XXX amplifiers would randomly lose network connectivity.